




TURN MACHINE OFF & REMOVE ALL POWER BEFORE BEGINNING



1

Put the wire in the connector

2

Fold the connector over the wire and squeeze with pliers until it locks

3

Plug the spade terminal directly into the tap connector

4

Now you have a secure and insulated connection

Kits For  
AC/DC 12V-240V